


OFFICE OF THE MARION COUNTY SURVEYOR
SECTION RECORD CORNER
SECTION 34 TOWNSHIP 15 RANGE 3
DATE: 11-8-99 7-1-05
PARTY CHIEF: Wilcoxon
CREW: _____
TYPE OF MARKER: Harrison
METHOD OF ESTABLISHMENT: County
EDM

IN. S.P.C. E ZONE, NAD 83
NAME: 15033405
N: 494329.4722(m)
E: 55384.9705(m)

NOTE: Set Harrison monument
where 1 1/2" pipe was found

THIS CORNER POSITION RE-
PRESENTS A "TITLE" CORNER
AND MAY NOT NECESSARILY
REPRESENT THE POSITION
BASED ON RECORD CORNERS



A survey by D. B. Hosbrook 6-19-1850 indicates no stone but witnesses: 10" hickory W 35 links; a white oak S 72 W 74 1/2 links per Perry Township Legal Survey Book pg. 18. Survey by Mayhew 10-8-1858 indicates that the center of Section is correct (per Perry Township Legal Survey Book pg. 18). Burres 10-5-48 called a railroad spike inside an iron pipe in concrete pavement. Hankins 9-1-60 called a railroad spike. McLand 4-17-73 called a railroad spike. Miller 10-14-75 called a railroad spike. Greene 2-11-87 called a railroad spike. Excavated 11-8-99 by Wilcoxon and set Harrison where the 1 1/2" pipe was recovered.

HC533405

REF.	DISTANCE	DESCRIPTION
1.	167.58'	Mag nail w/brass washer S public service pole #BAC 20' up
2.	20.86'	Due E to C/L control monument
3.	113.79'	Top nut of fire hydrant
4.	33.74'	Mag nail w/brass washer top wooden guard rail post
5.	28.66'	Mag nail w/brass washer N PwP#90-662B 30' up
6.	50.89'	Mag nail w/brass washer top wooden guard rail post